Bldg. 176
First Floor



MOLD KNOWN
ABOUT/REMEDIATED


EXISTING ELEV
EXISTING ELEV
RAMP
EXISTING RAMP
STAGING
NEW HYDRAULIC VERTICAL LIFT
SHIPPING/ RECEIVING
UP
EXISTING ELEV
UP
EXISTING STAIR #2
EXISTING STAIR

Bldg. 176
First Floor



WATER LEAK


EXISTING ELEV
EXISTING ELEV
RAMP
EXISTING RAMP
STAGING
NEW HYDRAULIC VERTICAL LIFT
SHIPPING/ RECEIVING
UP
EXISTING ELEV
UP
EXISTING STAIR #2
EXISTING STAIR
1225
1223
1217
1213
1207
1203
1211
1215
1209
1205
1201
1210
1206
1204
1202
1208
1400
1200
1500
1300
1100
1101
1100
1107
1105
1103
1113
1120
1118
1116
1112
1108
1104
1102
1114
1110
1106